




Бурт под фланец для стыковой сварки PP-H FIP (PN10) d110 SDR11 PN10

Артикул	d	h1	h3	S	Z	g
QBM11020	20	7	30	1,9	50	15
QBM11032	32	10	25	2,9	50	45
QBM11040	40	11	24	3,7	50	66
QBM11075	75	16	14	6,8	50	200
QBM11110	110	18	27	10	80	430
QBM11125	125	25	35	11,4	80	490
QBM11140	140	25	27	12,7	80	715
QBM11160	160	25	27	14,6	80	915
QBM11180	180	30	50	16,4	80	890
QBM11225	225	32	38	20,5	100	1780
QBM11250	250	35	25	22,7	100	2865
QBM11315	315	35	25	28,6	100	3500
QBM11400	400	46	95	36,3	195	10485
QBM11450	450	60	60	40,9	139	13350
QBM11500	500	60	60	45,4	138	12730
QBM11050	50	12	21	4,6	50	87
QBM11025	25	9	26	2,3	50	30
QBM11280	280	35	35	25,4	100	2600
QBM11090	90	17	33	8,2	80	322
QBM11200	200	32	28	18,2	100	1900
QBM11355	355	40	90	32,2	180	7730
QBM11063	63	14	16	5,8	50	129