




Отвод 90° для стыковой сварки PP-H FIP (PN 10) d50 SDR11 PN10

| Артикул  | d   | l  | r   | s    | Z   | g     |
|----------|-----|----|-----|------|-----|-------|
| GBM11020 | 20  | 3  | 24  | 1,9  | 27  | 5     |
| GBM11025 | 25  | 5  | 27  | 2,3  | 32  | 9     |
| GBM11032 | 32  | 5  | 35  | 2,9  | 40  | 17    |
| GBM11040 | 40  | 7  | 44  | 3,7  | 51  | 36    |
| GBM11050 | 50  | 7  | 55  | 4,6  | 62  | 66    |
| GBM11075 | 75  | 10 | 75  | 6,8  | 85  | 210   |
| GBM11090 | 90  | 10 | 90  | 8,2  | 100 | 355   |
| GBM11110 | 110 | 10 | 110 | 10   | 120 | 616   |
| GBM11125 | 125 | 15 | 125 | 11,4 | 140 | 945   |
| GBM11250 | 250 | 25 | 250 | 22,7 | 275 | 7210  |
| GBM11280 | 280 | 30 | 280 | 25,4 | 310 | 10020 |
| GBM11315 | 315 | 35 | 315 | 28,6 | 350 | 13965 |
| GBM11500 | 500 | 60 | 500 | 45,4 | 560 | 18500 |
| GBM11140 | 140 | 15 | 140 | 12,7 | 155 | 1300  |
| GBM11160 | 160 | 15 | 160 | 14,6 | 175 | 1870  |
| GBM11180 | 180 | 15 | 180 | 16,4 | 195 | 2767  |
| GBM11200 | 200 | 15 | 200 | 18,2 | 215 | 3604  |
| GBM11225 | 225 | 20 | 225 | 20,5 | 245 | 5292  |
| GBM11355 | 355 | 38 | 355 | 32,2 | 385 | 12760 |
| GBM11400 | 400 | 41 | 400 | 36,3 | 438 | 18500 |
| GBM11450 | 450 | 60 | 450 | 40,9 | 510 | 18500 |
| GBM11063 | 63  | 8  | 69  | 5,8  | 77  | 124   |