



# Муфта переходная для раструбной сварки PP-H IPS 63x40 PN10

| Артикул    | Размер | PN | DN     | D1  | D2  | d1  | d2 | L  | Z1 | Z2 | Вес  |
|------------|--------|----|--------|-----|-----|-----|----|----|----|----|------|
| IRIM075050 | 75x50  | 10 | 65x40  | 93  | 64  | 75  | 50 | 72 | 31 | 24 | 0,14 |
| IRIM075063 | 75x63  | 10 | 65x50  | 93  | 81  | 75  | 63 | 70 | 31 | 28 | 0,17 |
| IRIM090050 | 90x50  | 10 | 80x40  | 114 | 64  | 90  | 50 | 84 | 35 | 24 | 0,26 |
| IRIM110090 | 110x90 | 10 | 100x80 | 134 | 114 | 110 | 90 | 92 | 41 | 35 | 0,44 |
| IRIM040032 | 40x32  | 10 | 32x25  | 51  | 43  | 40  | 32 | 52 | 22 | 20 | 0,04 |
| IRIM063032 | 63x32  | 10 | 50x25  | 81  | 43  | 63  | 32 | 69 | 28 | 20 | 0,11 |
| IRIM110050 | 110x50 | 10 | 100x40 | 134 | 64  | 110 | 50 | 99 | 41 | 24 | 0,31 |
| IRIM032020 | 32x20  | 10 | 25x15  | 43  | 29  | 32  | 20 | 46 | 20 | 15 | 0,03 |
| IRIM025020 | 25x20  | 10 | 20x15  | 35  | 29  | 25  | 20 | 40 | 18 | 15 | 0,02 |
| IRIM032025 | 32x25  | 10 | 25x20  | 43  | 35  | 32  | 25 | 47 | 20 | 18 | 0,03 |
| IRIM040025 | 40x25  | 10 | 32x20  | 51  | 35  | 40  | 25 | 53 | 22 | 18 | 0,04 |
| IRIM050025 | 50x25  | 10 | 40x20  | 64  | 35  | 50  | 25 | 60 | 24 | 18 | 0,06 |
| IRIM050032 | 50x32  | 10 | 40x25  | 64  | 43  | 50  | 32 | 58 | 24 | 20 | 0,06 |
| IRIM050040 | 50x40  | 10 | 40x32  | 64  | 51  | 50  | 40 | 56 | 24 | 22 | 0,07 |
| IRIM063040 | 63x40  | 10 | 50x32  | 81  | 51  | 63  | 40 | 67 | 28 | 22 | 0,11 |
| IRIM063050 | 63x50  | 10 | 50x40  | 81  | 64  | 63  | 50 | 64 | 28 | 24 | 0,11 |
| IRIM090063 | 90x63  | 10 | 80x50  | 114 | 81  | 90  | 63 | 82 | 35 | 28 | 0,28 |
| IRIM090075 | 90x75  | 10 | 80x65  | 114 | 93  | 90  | 75 | 79 | 35 | 31 | 0,28 |
| IRIM110063 | 110x63 | 10 | 100x50 | 134 | 81  | 110 | 63 | 97 | 41 | 28 | 0,34 |
| IRIM110075 | 110x75 | 10 | 100x65 | 134 | 93  | 110 | 75 | 95 | 41 | 31 | 0,35 |
| IRIM075040 | 75x40  | 10 | 65x32  | 93  | 51  | 75  | 40 | 75 | 31 | 22 | 0,13 |