




Отвод 90° для раструбной сварки PP-H FIP d40 PN10

| Артикул | d   | DN  | PN | E   | H   | Z  | g   |
|---------|-----|-----|----|-----|-----|----|-----|
| GIM025  | 25  | 20  | 10 | 34  | 32  | 16 | 23  |
| GIM020  | 20  | 15  | 10 | 28  | 28  | 13 | 14  |
| GIM075  | 75  | 65  | 10 | 93  | 73  | 42 | 300 |
| GIM050  | 50  | 40  | 10 | 64  | 51  | 28 | 105 |
| GIM040  | 40  | 32  | 10 | 52  | 43  | 22 | 64  |
| GIM090  | 90  | 80  | 10 | 111 | 85  | 49 | 455 |
| GIM110  | 110 | 100 | 10 | 135 | 101 | 59 | 815 |
| GIM032  | 32  | 25  | 10 | 42  | 37  | 20 | 37  |
| GIM063  | 63  | 50  | 10 | 79  | 61  | 34 | 180 |