



Бурт под фланец для стыковой сварки PP-H FIP d90 SDR11 PN10

Артикул	d	h1	h3	S	Z	g		
QBM17050	50	11	24	2,3	50	60		
QBM17063	63	12	23	2.9	50	77		
QBM17090	90	16	35	4.3	50	180		
QBM17125	125	18	37	6.3	80	365		
QBM17140	140	18	42	7.1	80	390		
QBM17180	180	18	34	9.1	80	660		
QBM17200	200	20	30	10,2	80	610		
QBM17225	225	24	36	11.4	100	1440		
QBM17250	250	24	46	12.8	100	1290		
QBM17280	280	25	35	14.2	100	2035		
QBM17315	315	25	45	15.9	100	1825		
QBM17355	355	25	35	17,9	100	2525		
QBM17400	400	30	99	20.1	184	5460		
QBM17450	450	33	98	22.7	195	7120		
QBM17500	500	46	60	25.5	142	9935		
QBM17560	560	530	585	46	60	28.4	138	9195
QBM17630	630	615	685	50	60	31.7	139	13150
QBM17800	800	642	685	50	60	35.7	140	11685
QBM11020	20	7	30	1,9	50	15		
QBM11032	32	10	25	2,9	50	45		
QBM11040	40	11	24	3,7	50	66		
QBM11063	63	14	16	5,8	50	129		
QBM11090	90	17	33	8,2	80	322		
QBM11110	110	18	27	10	80	430		
QBM11125	125	25	35	11,4	80	490		
QBM11140	140	25	27	12,7	80	715		
QBM11180	180	30	50	16,4	80	890		
QBM11225	225	32	38	20,5	100	1780		
QBM11250	250	35	25	22,7	100	2865		

QBM11315	315	35	25	28,6	100	3500	
QBM11400	400	46	95	36,3	195	10485	
QBM11450	450	60	60	40,9	139	13350	
QBM11500	500	60	60	45,4	138	12730	
QBM17075	75	14	18	3,6	50	115	
QBM17110	110	17	43	5,1	80	280	
QBM17160	160	18	34	8	80	530	
QBM11025	25	9	26	2,3	50	30	
QBM11050	50	12	21	4,6	50	87	
QBM11075	75	16	14	6,8	50	200	
QBM11160	160	25	27	14,6	80	915	
QBM11200	200	32	28	18,2	100	1900	
QBM11280	280	35	35	25,4	100	2600	
QBM11355	355	40	90	32,2	180	7730	