



### Заглушка для стыковой сварки PP-H FIP (PN10) d250 SDR11 PN10

| Артикул  | d   | l   | S    | Z   | g     |
|----------|-----|-----|------|-----|-------|
| CBM11032 | 32  | 44  | 2,9  | 58  | 20    |
| CBM11050 | 50  | 55  | 4,6  | 75  | 50    |
| CBM11063 | 63  | 62  | 5,8  | 85  | 90    |
| CBM11090 | 90  | 79  | 8,2  | 110 | 230   |
| CBM11125 | 125 | 94  | 11,4 | 130 | 520   |
| CBM11180 | 180 | 141 | 16,4 | 191 | 730   |
| CBM11225 | 225 | 129 | 20,5 | 205 | 2625  |
| CBM11280 | 280 | -   | 25,4 | 55  | 2560  |
| CBM11315 | 315 | -   | 28,6 | 60  | 3600  |
| CBM11400 | 400 | -   | 36,3 | 70  | 7240  |
| CBM11500 | 500 | -   | 45,4 | 85  | 14000 |
| CBM11025 | 25  | 40  | 2,3  | 52  | 10    |
| CBM11040 | 40  | 50  | 3,7  | 67  | 30    |
| CBM11450 | 450 | -   | 40,9 | 80  | 10200 |
| CBM11355 | 355 | -   | 32,2 | 65  | 5040  |
| CBM11110 | 110 | 88  | 10   | 127 | 400   |
| CBM11140 | 140 | 99  | 12,7 | 142 | 695   |
| CBM11020 | 20  | 35  | 1,9  | 45  | 10    |
| CBM11200 | 200 | 127 | 18,2 | 181 | 1060  |
| CBM11250 | 250 | -   | 22,7 | 50  | 1840  |
| CBM11160 | 160 | 109 | 14,6 | 162 | 1040  |
| CBM11075 | 75  | 63  | 6,8  | 95  | 130   |