




Бурт для раструбной сварки PP-H FIP d40 PN10

| Артикул | d   | DN  | PN | b  | d3  | d4  | H  | Z | g   |
|---------|-----|-----|----|----|-----|-----|----|---|-----|
| QRNM020 | 20  | 15  | 10 | 7  | 27  | 45  | 20 | 6 | 12  |
| QRNM025 | 25  | 20  | 10 | 9  | 33  | 58  | 22 | 6 | 24  |
| QRNM032 | 32  | 25  | 10 | 10 | 41  | 68  | 25 | 6 | 36  |
| QRNM040 | 40  | 32  | 10 | 11 | 50  | 78  | 27 | 6 | 47  |
| QRNM050 | 50  | 40  | 10 | 12 | 61  | 88  | 30 | 6 | 63  |
| QRNM063 | 63  | 50  | 10 | 14 | 76  | 102 | 34 | 6 | 94  |
| QRNM075 | 75  | 65  | 10 | 16 | 90  | 122 | 38 | 6 | 149 |
| QRNM090 | 90  | 80  | 10 | 17 | 108 | 138 | 44 | 8 | 213 |
| QRNM110 | 110 | 110 | 10 | 18 | 131 | 158 | 50 | 8 | 297 |