



Муфта переходная для раструбной сварки PP-H IPS 32x20 PN10

Артикул	Размер	PN	DN	D1	D2	d1	d2	L	Z1	Z2	Вес
IRIM032020	32x20	10	25x15	43	29	32	20	46	20	15	0,03
IRIM032025	32x25	10	25x20	43	35	32	25	47	20	18	0,03
IRIM040025	40x25	10	32x20	51	35	40	25	53	22	18	0,04
IRIM040032	40x32	10	32x25	51	43	40	32	52	22	20	0,04
IRIM050032	50x32	10	40x25	64	43	50	32	58	24	20	0,06
IRIM050040	50x40	10	40x32	64	51	50	40	56	24	22	0,07
IRIM063032	63x32	10	50x25	81	43	63	32	69	28	20	0,11
IRIM063040	63x40	10	50x32	81	51	63	40	67	28	22	0,11
IRIM063050	63x50	10	50x40	81	64	63	50	64	28	24	0,11
IRIM075040	75x40	10	65x32	93	51	75	40	75	31	22	0,13
IRIM075050	75x50	10	65x40	93	64	75	50	72	31	24	0,14
IRIM075063	75x63	10	65x50	93	81	75	63	70	31	28	0,17
IRIM090050	90x50	10	80x40	114	64	90	50	84	35	24	0,26
IRIM090063	90x63	10	80x50	114	81	90	63	82	35	28	0,28
IRIM090075	90x75	10	80x65	114	93	90	75	79	35	31	0,28
IRIM110050	110x50	10	100x40	134	64	110	50	99	41	24	0,31
IRIM110063	110x63	10	100x50	134	81	110	63	97	41	28	0,34
IRIM110075	110x75	10	100x65	134	93	110	75	95	41	31	0,35
IRIM110090	110x90	10	100x80	134	114	110	90	92	41	35	0,44
IRIM025020	25x20	10	20x15	35	29	25	20	40	18	15	0,02
IRIM050025	50x25	10	40x20	64	35	50	25	60	24	18	0,06