




Бурт под фланец для стыковой сварки PP-H FIP (PN6) d110 SDR17.6 PN6

| Артикул  | d   | h1 | h3 | S    | Z   | g     |
|----------|-----|----|----|------|-----|-------|
| QBM17075 | 75  | 14 | 18 | 3,6  | 50  | 115   |
| QBM17125 | 125 | 18 | 37 | 6,3  | 80  | 365   |
| QBM17140 | 140 | 18 | 42 | 7,1  | 80  | 390   |
| QBM17180 | 180 | 18 | 34 | 9,1  | 80  | 660   |
| QBM17315 | 315 | 25 | 45 | 15,9 | 100 | 1825  |
| QBM17355 | 355 | 25 | 35 | 17,9 | 100 | 2525  |
| QBM17400 | 400 | 30 | 99 | 20,1 | 184 | 5460  |
| QBM17050 | 50  | 11 | 24 | 2,3  | 50  | 60    |
| QBM17110 | 110 | 17 | 43 | 5,1  | 80  | 280   |
| QBM17200 | 200 | 20 | 30 | 10,2 | 80  | 610   |
| QBM17225 | 225 | 24 | 36 | 11,4 | 100 | 1440  |
| QBM17280 | 280 | 25 | 35 | 14,2 | 100 | 2035  |
| QBM17450 | 450 | 33 | 98 | 22,7 | 195 | 7120  |
| QBM17090 | 90  | 16 | 35 | 4,3  | 50  | 180   |
| QBM17800 | 800 | 50 | 60 | 35,7 | 140 | 11685 |
| QBM17063 | 63  | 12 | 23 | 2,9  | 50  | 77    |
| QBM17160 | 160 | 18 | 34 | 8    | 80  | 530   |
| QBM17250 | 250 | 24 | 46 | 12,8 | 100 | 1290  |
| QBM17500 | 500 | 46 | 60 | 25,5 | 142 | 9935  |
| QBM17560 | 560 | 46 | 60 | 28,4 | 138 | 9195  |
| QBM17630 | 630 | 50 | 60 | 31,7 | 139 | 13150 |