




Переходная муфта с ВР, раструбная сварка РР-Н FIP 25x3/4 PN10

| Артикул    | d x R     | PN | E  | H  | Z | g   |
|------------|-----------|----|----|----|---|-----|
| MIMM020012 | 20 x 1/2" | 10 | 30 | 39 | 8 | 14  |
| MIMM032100 | 32 x 1"   | 10 | 47 | 45 | 7 | 40  |
| MIMM050112 | 50 x 1½"  | 10 | 66 | 55 | 9 | 92  |
| MIMM063200 | 63 x 2"   | 10 | 83 | 63 | 9 | 150 |
| MIMM025034 | 25 x 3/4" | 10 | 39 | 41 | 8 | 23  |
| MIMM040114 | 40 x 1¼"  | 10 | 55 | 50 | 8 | 46  |