




Отвод 45° для раструбной сварки PP-H FIP d75 PN10

| Артикул | d   | DN  | PN | E   | H  | Z    | g   |
|---------|-----|-----|----|-----|----|------|-----|
| HIM110  | 110 | 100 | 10 | 135 | 71 | 28   | 610 |
| HIM025  | 25  | 20  | 10 | 34  | 25 | 9    | 19  |
| HIM040  | 40  | 32  | 10 | 52  | 36 | 15   | 57  |
| HIM063  | 63  | 50  | 10 | 79  | 51 | 24   | 182 |
| HIM090  | 90  | 80  | 10 | 113 | 61 | 23,5 | 335 |
| HIM020  | 20  | 15  | 10 | 28  | 21 | 7    | 12  |
| HIM050  | 50  | 40  | 10 | 63  | 43 | 19   | 105 |
| HIM032  | 32  | 25  | 10 | 42  | 29 | 12   | 33  |
| HIM075  | 75  | 65  | 10 | 92  | 53 | 20   | 200 |