



Бурт под фланец для стыковой сварки PP-H FIP d355 SDR11 PN10

| Артикул  | d   | h1  | h3  | S    | Z   | g    |     |       |
|----------|-----|-----|-----|------|-----|------|-----|-------|
| QBM17050 | 50  | 11  | 24  | 2,3  | 50  | 60   |     |       |
| QBM17063 | 63  | 12  | 23  | 2.9  | 50  | 77   |     |       |
| QBM17075 | 75  | 14  | 18  | 3.6  | 50  | 115  |     |       |
| QBM17090 | 90  | 16  | 35  | 4.3  | 50  | 180  |     |       |
| QBM17125 | 125 | 18  | 37  | 6.3  | 80  | 365  |     |       |
| QBM17110 | 110 | 17  | 43  | 5,1  | 80  | 280  |     |       |
| QBM17140 | 140 | 18  | 42  | 7.1  | 80  | 390  |     |       |
| QBM17160 | 160 | 18  | 34  | 8    | 80  | 530  |     |       |
| QBM17180 | 180 | 18  | 34  | 9.1  | 80  | 660  |     |       |
| QBM17200 | 200 | 20  | 30  | 10,2 | 80  | 610  |     |       |
| QBM17225 | 225 | 24  | 36  | 11.4 | 100 | 1440 |     |       |
| QBM17250 | 250 | 24  | 46  | 12.8 | 100 | 1290 |     |       |
| QBM17280 | 280 | 25  | 35  | 14.2 | 100 | 2035 |     |       |
| QBM17315 | 315 | 25  | 45  | 15.9 | 100 | 1825 |     |       |
| QBM17355 | 355 | 25  | 35  | 17,9 | 100 | 2525 |     |       |
| QBM17400 | 400 | 30  | 99  | 20.1 | 184 | 5460 |     |       |
| QBM17450 | 450 | 33  | 98  | 22.7 | 195 | 7120 |     |       |
| QBM17500 | 500 | 46  | 60  | 25.5 | 142 | 9935 |     |       |
| QBM17560 | 560 | 530 | 585 | 46   | 60  | 28.4 | 138 | 9195  |
| QBM17630 | 630 | 615 | 685 | 50   | 60  | 31.7 | 139 | 13150 |
| QBM17800 | 800 | 642 | 685 | 50   | 60  | 35.7 | 140 | 11685 |
| QBM11020 | 20  | 7   | 30  | 1,9  | 50  | 15   |     |       |
| QBM11025 | 25  | 9   | 26  | 2,3  | 50  | 30   |     |       |
| QBM11032 | 32  | 10  | 25  | 2,9  | 50  | 45   |     |       |
| QBM11040 | 40  | 11  | 24  | 3,7  | 50  | 66   |     |       |
| QBM11050 | 50  | 12  | 21  | 4,6  | 50  | 87   |     |       |
| QBM11063 | 63  | 14  | 16  | 5,8  | 50  | 129  |     |       |
| QBM11075 | 75  | 16  | 14  | 6,8  | 50  | 200  |     |       |
| QBM11090 | 90  | 17  | 33  | 8,2  | 80  | 322  |     |       |

|          |     |    |    |      |     |       |  |
|----------|-----|----|----|------|-----|-------|--|
| QBM11110 | 110 | 18 | 27 | 10   | 80  | 430   |  |
| QBM11125 | 125 | 25 | 35 | 11,4 | 80  | 490   |  |
| QBM11140 | 140 | 25 | 27 | 12,7 | 80  | 715   |  |
| QBM11160 | 160 | 25 | 27 | 14,6 | 80  | 915   |  |
| QBM11180 | 180 | 30 | 50 | 16,4 | 80  | 890   |  |
| QBM11200 | 200 | 32 | 28 | 18,2 | 100 | 1900  |  |
| QBM11225 | 225 | 32 | 38 | 20,5 | 100 | 1780  |  |
| QBM11250 | 250 | 35 | 25 | 22,7 | 100 | 2865  |  |
| QBM11280 | 280 | 35 | 35 | 25,4 | 100 | 2600  |  |
| QBM11315 | 315 | 35 | 25 | 28,6 | 100 | 3500  |  |
| QBM11355 | 355 | 40 | 90 | 32,2 | 180 | 7730  |  |
| QBM11400 | 400 | 46 | 95 | 36,3 | 195 | 10485 |  |
| QBM11450 | 450 | 60 | 60 | 40,9 | 139 | 13350 |  |
| QBM11500 | 500 | 60 | 60 | 45,4 | 138 | 12730 |  |